

AD-A112 182

ARMY ENGINEER DISTRICT PHILADELPHIA PA

F/G 13/13

BELTZVILLE LAKE CONDITION REPORT, DAM, OUTLET WORKS AND SPILLWA--ETC(U)

JUN 74

UNCLASSIFIED


DAEN/NAP-01340/PIR0304-74

NL


1 OF 2

AD-A

112182



2182



AD A 112182

LEHIGH RIVER BASIN  
POHOPOCO CREEK, PENNSYLVANIA  
**BELTZVILLE LAKE**

CONDITION REPORT

DAM, OUTLET WORKS & SPILLWAY,  
PERIODIC INSPECTION REPORTS NO. 3 & NO. 4,  
SEPTEMBER 1972 & AUGUST 1973

APPROVED FOR PUBLIC RELEASE;  
DISTRIBUTION UNLIMITED.

Copy available to DTIC does not  
permit fully legible reproduction



DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE - 2D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

JUNE 1974

82 03 17 112

REPORT NO. DAEN/NAP-01340/PIR304-74/06

DTIC FILE COPY

DTIC  
MAR 18 1982

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER DAEN/NAP-01340/PIRO304-74/06	2. GOVT ACCESSION NO. 70-A112-182	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Beltzville Lake condition report, dam, outlet works & spillway, periodic inspection reports No. 3 & 4, Sept. 1972 & August 1973.		5. TYPE OF REPORT & PERIOD COVERED Periodic inspection report
7. AUTHOR(s)		6. PERFORMING ORG. REPORT NUMBER DAEN/NAP-01340/PIRO304-74/06
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, Philadelphia 2nd & Chestnut Sts. Philadelphia, PA 19106		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE June, 1974
		13. NUMBER OF PAGES 54
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)  Beltzville Lake, Pa. Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  The third periodic inspection of Beltzville Dam was held on 14 and 15 September. Installation of two additional weirs and a study of seepage was requested. During the fourth periodic inspection on 23-24 August 1973 it was reported that weir records showed no increase in base flows thus indicating a stabilized seepage flow which is of minimal volume.  Instrumentation installed appeared to be adequately monitoring dam performance. The overall condition of the project was considered excellent.		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED  
FROM THE BEST COPY FURNISHED BY  
THE SPONSORING AGENCY. ALTHOUGH  
IT IS RECOGNIZED THAT CERTAIN POR-  
TIONS ARE ILLEGIBLE, IT IS BEING  
RELEASED IN THE INTEREST OF MAKING  
AVAILABLE AS MUCH INFORMATION AS  
POSSIBLE.







DEPARTMENT OF THE ARMY  
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS  
CUSTOM HOUSE-2 D & CHESTNUT STREETS  
PHILADELPHIA, PENNSYLVANIA 19106

IN REPLY REFER TO

NAPEN-F

5 July 1974

SUBJECT: Peltzville Lake, Periodic Inspection Report Number 3 & 4.

Division Engineer, North Atlantic  
ATTN: NADEN

In accordance with the instructions contained in ER 1110-2-100, "Periodic Inspection and Continuing Evaluation of Civil Works Projects", the subject report is transmitted for your review and approval.

FOR THE DISTRICT ENGINEER:

1 Incl (6 cys)

*Worth D Phillips*  
WORTH D. PHILLIPS  
Chief, Engineering Division

Condition Report  
Beltzville Lake  
Pohopoco Creek, Pennsylvania

Periodic Inspection Report No. 3 & 4

Table of Contents

<u>Section</u>	<u>Title</u>	<u>Page</u>
1	Authority and Scope	1
2	Construction History	1
3	Inspection and Evaluation	2
4	Personnel	2
5	Results of Third Periodic Inspection	2
6	Results of Fourth Periodic Inspection	7
7	Corrective Measures	13
8	Seepage Study	16
9	Results of Instrumentation	19
10	Environmental Quality Control Equipment	26
11	Summary	28

PLATES

<u>No.</u>	<u>Title</u>
1.	General Plan
2.	Piezometer Data 1969-1970
3.	Piezometer Data 1971-1972
4.	Piezometer Data 1973-1974
5.	Instrumentation Line @ Station 7+770
6.	Instrumentation Line @ Station 8+600 & 9+280
7.	Instrumentation Line @ Station 9+580 & 9+820
8.	Surface Settlement Pipe Plan
9.	Subsurface Settlement Data VIF 92-2 1969-1970
10.	Subsurface Settlement Data VIF 92-2 1971-1972
11.	Subsurface Settlement Data VIF 92-2 1973-1974
12.	Subsurface Settlement Data VIF 95-2 1969-1970
13.	Subsurface Settlement Data VIF 95-2 1971-1972
14.	Subsurface Settlement Data VIF 95-2 1973-1974
15.	Subsurface Settlement Data VIF 98-5 1969-1970
16.	Subsurface Settlement Data VIF 98-5 1971-1972
17.	Subsurface Settlement Data VIF 98-5 1973-1974
18.	Weir Discharge Study
19.	Flow Net Construction Station 9+580

## Appendix A

### Supplemental As-Built Drawings

<u>Plate No.</u>	<u>Title</u>
20	Outlet Works Excavation - General Plan
21	Outlet Works Excavation - Sections
22	Geological Profile on Axis of Dam and Grout Curtain
23	Typical Sections - Dam
24	Typical Sections - Dam
25	Grouting Plan and Details
26	Instrumentation Plan and Details
27	Instrumentation Details
28	Conduit-Geological Profile on & Conduit
29	Conduit-Outline and Reinforcement
30	Geologic Profiles Showing Berm Locations-Outlet Works
31	Concrete Structures-Outline and Reinforcement-Spillway
32	Concrete Structures-Outline and Reinforcement-Spillway
33	Elevation and Structural Details - Service Bridge
34	Elevation and Structural Details - Spillway Bridge

## Appendix B

List of Attendees - Periodic Inspections Nos. 3 & 4

INSPECTION & ACTION SUMMARY  
PERIODIC INSPECTION REPORT NO. 3 & 4

Item	Summary of Comment(s)	Action
1. Abutment & embankment junctions.	Erosion noted at downstream and upstream contacts of embankment with right abutment. Boulders placed on downstream junction during construction to reduce erosion have been only partially effective condition noted in Periodic Inspections 1,2,3 & 4.	I am operating personnel are filling and regrading the upstream contact area to provide drainage away from riprap toe. No action has been taken or is contemplated at present for the downstream area since condition of contact area is stable.
2. Sloughing or erosion of embankment slopes.	Resistance of material on downstream slopes to weathering & possible eventual clogging of horizontal drain with migrating fines was questioned during Periodic Inspection #1; minor erosion paths in downstream slope were noted during Periodic Inspection No. 2; no problems noted during Periodic Inspections 3 & 4.	Slope has been closely observed for sloughing and erosion by operating personnel. Piezometers indicate no pressure increases attributable to ineffectiveness of horizontal drain. Gradation of drain should preclude infiltration.
3. Spillway - Weepholes and drainage system.	Some weepholes in spillway slab clogged with dirt and needed cleaning (Periodic Inspection No. 1); installation of screens to prevent clogging & entry of burrowing animals recommended (Periodic Inspections 1,2,3).	Screens were installed following third periodic inspection.
4. Outlet Works Conduit concrete surfaces and cracks.	Minor cracking in transition zone, conduit and tower sections noted in Periodic Inspections 1 & 2, crack survey and updating recommended. Minor spalling noted in Periodic Inspections 2,3 & 4.	Crack survey was made following Periodic Inspection No. 1 and updated after Periodic Inspection No. 2. No further action planned at this time.

5. Seepage Condition (Embankment and/or foundation).  
Small springs noted along left abutment downstream of dam (Periodic Inspection No. 2); seeps in rock cut to right of stilling basin had begun during preceding winter & continued throughout the summer, base flow of seepage along left abutment had increased during filling of the reservoir (Periodic Inspection No. 3). Installation and monitoring of weir system (Inspections 2 & 3) and seepage study (Periodic Inspection No. 3) recommended.  
Weirs installed, maintained and monitored. Evaluation of seepage condition submitted (Para 8, Periodic Inspection Report No. 3 and 4). Monitoring of weirs by operating personnel will continue on current schedule.
6. Outlet Works - Joints and joint material.  
Leakage noted at construction joints 2+53.59 (Periodic Inspection No. 2) and 11+53.59 (Periodic Inspections 2, 3 & 4). Minor spalling at construction joints noted during all inspections. Spalls appear to be result of patch failures.  
Joints will be monitored by Periodic Inspection Teams for further deterioration. No further action recommended at this time.
7. Outlet Works - Water passages including drains.  
Replacement of missing pressure cell cover plate recommended (Periodic Inspection No. 2 & 3).  
Pressure cell cover replaced in spring 1973.
8. Spillway - Concrete surfaces.  
Hairline cracking and poor surface appearance noted (Periodic Inspection No. 1); no changes in appearance or condition noted in Periodic Inspections Nos. 2, 3 & 4 except for some new spalling in center slabs upstream of bridge piers (Periodic Inspection No. 3).  
Crack survey completed following Periodic Inspection No. 2.
9. Spillway - Joint displacement and joint material.  
Extrusion of pre-molded joint material along the left side of the north spillway bridge pier due to closure of joint (Periodic Inspections No. 1, 2, 3 & 4). Joint space on right side of pier has opened to extend that of pre-molded does not cover joint (Periodic Inspection No. 4).  
North bridge pier will be monitored to determine if joint action is the result of pier movement. Condition of joint material will be observed to determine need for replacement.

10. Miscellaneous -  
Fencing.

Fencing located at lower bridge abutment, designed to prevent entrance by unauthorized personnel, is inadequate. (Periodic Inspection No. 2).

Security fence was modified to prohibit access by unauthorized personnel following periodic inspection No. 2.

11. Miscellaneous -  
Saw Mill Run  
erosion ditch.

A ditch running from the downstream toe to Saw Mill Run had been badly eroded. Steep banks, 20 to 25 feet high with overhanging trees, presented a safety hazard to the Public. (Periodic Inspection Report No. 2)

Work on a drainage pipe commenced following periodic inspection No. 2 and was completed and performing satisfactorily prior to periodic inspection No. 4.

12. Miscellaneous -  
Access Road entrance speed  
reduction.

Because of combination of vertical and horizontal curves on the relocated highway in the vicinity of the entrance to the public overlook area, sight distance were considered marginal. Recommendation to approach state highway officials to consider reduction of speed limit in this area of the public highway. (Periodic Inspection No. 2)

No formal action taken. No complaints from public or accidents have been reported to the District.

13. Intake Tower  
Equipment -  
water quality  
control gates  
and hoists.

Gate does not close completely, having an opening of 0.4 inches in closed position. (Periodic Inspection No. 3); Control gate leaks around stem seal at specific gate settings. (Periodic Inspection No. 4)

Control gate can be closed manually should the need arise for complete closure-no further action contemplated. Gate stem seal leak will be studied by District personnel.

14. Intake Tower  
Equipment -  
Sluice gate  
and hoist.

Number 1 sluice gate had a bent stem and cracked casing and indicators were loose. (Periodic Inspection No. 3)

Stem and casing repaired; adjustments made to prevent recurrence.

15. Intake Tower Equipment - Elevator	Elevator was not operational at the time of Periodic Inspection No. 3. Primary causes of problem were shorts in the power cable and corrosion of relay contacts due to high humidity in the tower.	Permanent repairs completed after Periodic Inspection No. 3. Maintenance contractor keeping elevator in working order.
16. Intake Tower Equipment - Electrical (general).	Water present in electrical conduits and boxes at lower elevations. Recommended surface mounting of boxes and repair of dead portable heater socket @ EL.548. (Periodic Inspection No. 3). Most work completed with exception of a few receptacles still to be reset (Periodic Inspection No. 4).	District electrician has rewired lower tower elevations and provided for drainage of water in conduits.
17. Intake Tower Equipment - Heating (general).	Providing adequate heating in lower levels of the tower recognized as a problem, study of problem and initiation of corrective measures recommended. (Periodic Inspection No. 3).	Study and corrective measures completed.
18. Spillway - Bridge guard rails.	Many nuts holding guard rail to bridge parapet were not tight against railing base. (Periodic Inspection No. 3).	Nuts tightened after Periodic Inspection No. 3).
19. Spillway - Side slopes.	Erosion noted along right side of spillway cut upstream of chute (Periodic Inspection No. 3); extent of weathering of slope questioned, comparison of present condition with description from construction files to determine extent recommended (Periodic Inspection No. 4).	Operating personnel are correcting erosion problem by extending top of slope drainage ditch past eroding area. Inspection will be made, construction files for photos and comparison with existing conditions will be made.



20. Recreation Area - Boat launching ramp.  
State park managers and dam operating personnel reported a potentially dangerous situation. During first summer of operation, two cars has rolled down ramp into 10 to 15 feet of water will launching or landing boats. (Periodic Inspection No. 3).  
Boat launching ramps are being swept clean of loose gravel which had apparently contributed to former problems. No further problems reported.
21. Intake Tower  
Equipment - Emergency engine generator.  
Hydraulic starter for emergency engine generator is difficult to reprime when engine fails to start, requires 20 minutes to reprime using hand crank.  
Problem will be investigated by District personnel as funds become available for the study.
22. Stilling Basin  
- Outlet channel side slopes.  
Outlet channel side slopes have suffered erosion on both banks due to extremely high releases during conduit gate rating and prototype testing in spring 1973. Most seriously eroded area is on right bank immediately downstream of stilling basin.  
(Periodic Inspection No. 4).  
Tenatively plan to riprap areas to prevent further erosion.  
Final plans and construction will be accomplished as funds become available.
23. Embankment - Movement of structural features. Service bridge to tower.  
Small northward horizontal movement recorded by tower bridge alignment survey. Present quantity of movement presents no danger to structure.  
(Periodic Inspection No. 4).  
District continuing observations on regular schedule. No further action scheduled.
24. Spillway - Upstream wet area.  
Wet area observed in upstream end of spillway; recommended drainage by shallow trenching if site conditions permit (Periodic Inspection No. 4).  
District to survey area to determine drainage feasibility.

Beltzville Lake  
Pohopoco Creek, Pennsylvania  
Dam, Outlet Works and Spillway

Periodic Inspection Report No. 3 and 4

1. AUTHORITY AND SCOPE

This report has been prepared in accordance with Engineer Regulation 1110-2-100, entitled "Periodic Inspection and Continuing Evaluation of Completed Civil Works Structures".

Due to the emergency workload and priorities generated by tropical storm "Agnes" which occurred during June 1972, the report submission for the third periodic inspection of Beltzville Lake was delayed to the extent of overlapping the fourth periodic inspection. At the time of the fourth periodic inspection, District representatives requested approval of presenting both the third periodic inspection, conducted 14-15 September 1972, and the fourth periodic inspection, conducted 23-24 August 1973, in one report. Approval was received at a later date and this report accordingly presents results of both inspections. In addition, this report presents instrumentation readings obtained subsequent to the second periodic inspection, updates the construction history of the project, presents remedial measures adopted by the District and provides a brief evaluation study of seepage noted at the downstream toe of the embankment. The report also includes a presentation of the environmental quality control equipment presently installed and a summary of the difficulties experienced to date with this equipment.

In accordance with ERMW-PZ 2nd indorsement to DA basic transmittal letter dated 4 February 1971, subject "Beltzville Lake, Periodic Inspection Report No. 1", as-built drawings showing significant project features are included in Appendix A of this report. The appendix is intended to supplement the as-built drawings presented in the first periodic inspection report for Beltzville Lake and will be referred to in future periodic inspection reports for specific as-built details of the project.

2. CONSTRUCTION HISTORY

The construction history of dam site facilities and Phase I clearing contract to elevation 586, were presented in Periodic Inspection Report No. 2.

The Phase II clearing, awarded 18 July 1970 to Demolition of Buffalo Corporation, consisted of clearing and grubbing the portion of the reservoir area between elevation 586 and elevation 628, normal operating level. The Phase II clearing was completed on 16 July 1971 at a cost of \$189,400.

The recreation contract, awarded 1 September 1970 to A. I. Proctor Company, Incorporated, consisted of construction of a boat launching ramp, parking area, appropriate change facilities, picnic area, roads and grouting facilities and a sewage treatment plant downstream of the embankment. The recreation contract was completed on 15 May 1972 at a total cost of \$1,300,000.

#### 3. INSPECTION PROGRAM, A-1

As required by FHWA-4-100 "Periodic Inspection and Continuing Evaluation of Completed Civil Works Structures", a system of continuing evaluation including periodic inspection was planned to assure the safety and stability of the Belzville Lake Project. These periodic inspections are planned to locate problem areas and to provide a basis for recommendations of remedial treatment if and when required. Periodic inspections for Belzville Lake have been performed or are tentatively scheduled in the following sequence:

<u>Inspection</u>	<u>Time Interval</u>	<u>Scheduled Date</u>	<u>Actual Date</u>
Initial		July 1970	20 July 70
1st Periodic	1 year	July 1971	22 July 71
2nd Periodic	1 year	July 1972	14-15 Sep 72
3rd Periodic	1 year	July 1973	23-24 Aug 73
4th Periodic	1 year	July 1974	-
5th Periodic	1 year	July 1975	-
6th Periodic	2 years	July 1977	-
7th Periodic	2 years	July 1979	-
8th Periodic			-

The inspection following the two year interval will be increased to a one year frequency if justified by the results of previous inspections.

#### 4. ATTENDANCE

The third and fourth periodic inspections were attended by representatives of North Atlantic Division and Philadelphia District. Lists of those attending are included in Appendix B.

#### 5. RESULTS OF PERIODIC INSPECTION - 14 & 15 SEPTEMBER 1972

Pool elevation at the time of the inspection was Elevation 627.3 which is 17.0 feet below the normal pool elevation of 628 and is 125.3 feet above the normal pre-impoundment river elevation. The reservoir has reached normal pool elevation on 18 Dec 1971, and with some fluctuation (about 10 feet) had remained at that elevation until the time of the inspection.

Upon arrival at the project site, the inspection party was briefed on the results of the first two periodic inspections. Reports of the 2nd periodic inspection were made available to the team members to familiarize them with the project and its condition at the time of the inspection. A review of the instrumentation data collected since the last inspection was made prior to initiating the inspection and a detailed check list was supplied to each party member for use during the inspection. The party inspected the intake tower, conduit, settling basin, enlargement and spillway areas on 14 September 1972. On 15 September 1972, the party inspected the reservoir area, including the recreation area.

Following the inspection, a critique was held in the project office in which discussion followed the checklist which had been furnished. All comments made at this critique were noted and are summarized in the following paragraphs:

(1) Intake Tower

a) Service bridge

- (1) Concrete surfaces - good condition
- (2) Concrete cracks - none noted
- (3) Expansion joints - good condition
- (4) Drainage system - good condition
- (5) Structural steel - good condition
- (6) Bearings - good condition
- (7) Guard rails & fencing - good condition
- (8) Bridge movement - none noted.

b) Intake Tower

(1) Structural - concrete surfaces (cracks and leakage) - No major deficiencies were noted. Minor cracking noted in top deck of tower. Some minor leakage at joints and from tie locations below pool level.

c) Equipment

- (1) Service gates and hoists - no deficiencies noted
- (2) Emergency gates and hoists - no deficiencies noted
- (3) Water quality control gates and hoists - gate does not close completely having an opening of 0.4 inches in the closed position. Study of this problem and possible remedial treatment has been initiated.
- (4) Sluice gates and hoist - The number 1 sluice gate has a bent stem and cracked casing and indicators are loose. The problems are under study and the stem and casing will be replaced and indicators repaired.

Elevator - The elevator was not operational at the time of the inspection. Inspection & repair of the system was accomplished by factory representatives during the week of 17 Sept 1972. Shorts in the power cable and corrosion of relay contacts due to high humidity in the tower are the primary causes of these operational problems. A study of the humidity problem and possible corrective measures has been initiated.

Pump pump and by-pass drain - no deficiencies noted.

Electrical - general - water is present in electrical conduits and boxes at lower elevations. Surface mounting of outlets to prevent trapping of water & repair of one dead portable heater socket at El. 548 was recommended.

General - providing for heat in the lower levels of the tower is a problem. A study of this problem and possible corrective measures has been initiated.

(c) Conduit and Stilling Basin

(a) Conduit

Concrete surfaces - no deficiencies, except for minor spalling, were noted. Location and extent of spalling virtually unchanged from those noted in 1971 survey.

Concrete cracks - location and extent of cracking was virtually unchanged from those noted in 1971 survey.

Leakage - no new leakage was noted, leakage thru cracks and joints was less than that noted in last condition survey, primarily due to calcite deposits sealing cracks.

Joints - overall condition good, minor spalling at joints shows little change since last condition survey. Some leakage at joint at Sta 11 + 53.5 was noted.

Water passages including drains - cover plate missing at pressure cell location T-6 in water quality control outlet; cover plate will be replaced after completion of repairs to water quality control gate stem.

(b) Stilling Basin

1) Concrete surfaces - in good condition, no deficiencies noted.

2) Concrete cracks - minor, no change since last inspection.

3) Leakage - none noted

4) Joints - minor spalling noted at vertical contraction joints on left wall.

5) Drains - all drains and weepholes appear to be open and functional.

(3) Embankment

- a) Surface cracks - none noted
- b) Abutment and embankment junctions - no deficiencies noted.
- c) Vertical and Horizontal Alignment - minor movements revealed by surveys and instrumentation data are consistent with anticipated behavior.
- d) Unusual movement or cracking at toe - none noted.
- e) Unusual through embankment or downstream seepage - A seep in the rock cut to the right of the stilling basin was noted during the winter and early spring of 1972 and had continued to flow throughout the summer to the time of the inspection. This seep appears to have a base flow of approximately 0.025 cfs based on 8 months of weir readings. The base flow of the seepage emerging at the junction of the downstream toe of the dam and the left abutment (See Condition Report No. 2 for photographs and additional discussion) had increased from 0.2 to 0.3 cfs during the filling of the reservoir in 1971-1972. Measurements of this flow were made at a weir installed in August 1971. A more complete discussion of this downstream seepage is included in Section 8 of this report.
- f) Sloughing or erosion of embankment or abutment slopes - Erosion at the junction of the downstream toe of the embankment and the right abutment in the vicinity of the stilling basin, noted in previous inspections, has continued.

The inspection team recommended a detailed study of the problem be made to determine the best remedial measures and that the corrective measures be implemented prior to the next scheduled inspection. Without benefit of a detailed study of the problem, installation of a paved ditch along this junction appears the most feasible solution.

- g) Movement of structural features in the embankment - none noted.
- h) Riprap failure (major displacement) - none noted.

(4) Spillway

(a) Bridge

- (1) Concrete surfaces - good condition, no deficiencies noted.
- (2) Concrete cracks - none noted
- (3) Expansion joints - Expansion joint at the north abutment requires cleaning and replacement of joint material.
- (4) Drainage system - no deficiencies noted.
- (5) Structural steel - no deficiencies noted.
- (6) Bearings - no deficiencies noted.

- (f) Guard rails - many nuts holding guard rail to bridge parapet are not tight against the railing base; nuts should be tightened to required torque.
  - (g) Bridge movement - none noted.
- (b) Gate and Gravity Walls
- (1) Concrete surfaces - some new spalling was noted in the center slabs upstream of the bridge, the condition of remainder of the chute is the same as noted during the 1971 survey.
  - (2) Concrete cracks - no appreciable change since 1971 condition survey.
  - (3) Expansion joints (material and displacement) - expansion joints show little change from that noted in 1971 inspection. Possible replacement following next inspection judging from present condition.
  - (4) Drainage system - general condition is good. Inspection team recommended installation of screens at outlet end of collector pipes to prevent entry of animals and possible blockage.
  - (5) Leakage - none noted.
- (c) Other Miscellaneous
- (1) Spillway side slope - erosion noted along right side of spillway cut upstream of chute. Repair of eroded section and installation of slope pipe to carry flow was recommended.
  - (2) Miscellaneous - In answer to head dam operator's question, team recommended cutting saplings which are growing in upstream section of spillway before additional growth makes removal difficult.
- (5) Downstream Area
- (a) Erosion and Drainage - see comment (3)(f).
  - (b) Surface cracking - none noted.
  - (c) Weirs - Team recommended reinstallation of weir in ditch to right of stilling basin and installation of weir at upstream end of pool to determine quantity of seepage from zone noted at left abutment and downstream toe junction.
  - (d) Sawmill Run erosion area - work has been initiated on the major remedial work in this area and was progressing satisfactorily at the time of the inspection.

(c) Upstream Reservoir Areas

- a) Erosion of reservoir side slopes - none noted.
- b) Condition of highway embankment riprap - condition good at all embankments inspected.
- c) Concrete ditches - no deficiencies noted.
- d) Highway bridges - no deficiencies noted.
- e) Recreation area - condition generally satisfactory. State park Manager and federal dam tenders reported a potentially dangerous situation at the boat launching ramp. During first summer's operation, two cars rolled back down the launching ramp and did not stop until covered with 10 to 15 feet of water. In one of these cases, the vehicle was in "Park" transmission position, the emergency break was on and a wheel or wheels were chocked. In spite of these precautions, the loads induced while pulling the boat onto its trailer were enough to override these precautions. Although neither incident resulted in any more than vehicle damage, State and federal personnel expressed concern over the danger of personal injuries or deaths in a case of recurrence. Apparently it is common practice for people (including children) to remain in the towing vehicle while a boat is being off or on loaded onto a boat trailer. Based on the demonstrated danger of this facility, it is recommended that some sort of barrier be installed to prevent cars and trailers from rolling into deep water because of the relatively steep slope of the ramp and lack of any obstruction to such movement. This barrier should be placed so as to allow approximately 4' between the top of the barrier and the water surface. The barrier should also be movable to allow its placement to provide the aforementioned clearance under fluctuating pool conditions.

C. RESULTS OF FOURTH PERIODIC INSPECTION - 23 & 24 AUGUST 1973

Pool elevation at the time of the inspection was 628, which is the normal operating reservoir elevation. Minimal fluctuation in pool level, within one foot of the operating reservoir level, is normally maintained by operating personnel except during periods of excessive rainfall.

The inspection party was briefed on the results of the first three periodic inspections and furnished with comments from the third periodic inspection. Updated instrumentation readings were presented and discussed together with results of a preliminary analysis of embankment seepage. A detailed check list was then supplied for use during the inspection. The party inspected the intake tower, downstream contact and seepage zone, conduit, spillway and sewage treatment plant areas during the first day and the upstream contact zone, roadway bridges, roadway embankments and recreation areas during the morning of the second day.



Following the inspection, a critique was conducted in the project office based on the checklist which has been furnished. All comments made at the critique were recorded and are summarized in the following paragraphs:

(1) Instrumentation Data Review of settlement point, piezometer and VI: data revealed no unusual conditions, with the exception of the movement of settlement point SP-5. This point, located at Station 8 + 901 has settled 0.24 feet (about 0.5% of embankment height) and moved horizontally 0.14 feet away from the centerline in the three year period from 9 July 1970 to 3 July 1973. Other surface settlement points in this vicinity (8 + 400 to 9 + 230) have settled no more than 0.25 feet and moved horizontally 0.09 feet or less. The installation at SP-5 was inspected by the team and was in satisfactory condition. There is no evidence of distress in the embankment in this area and it is concluded that the settlement is due to locally greater consolidation of the fill. Monitoring of all instrumentation will continue on the present schedule.

(2) Intake Tower

(a) Service Bridge

- (1) Concrete Surfaces - Minor spalling noted at deck slab-parapet intersection.
- (2) Concrete Cracks - None noted
- (3) Expansion Joints - Joint sealer at joints between spans is deteriorating. Replacement necessary in near future
- (4) Drainage System - No deficiencies noted
- (5) Structural Steel - Paint beginning to show signs of age. Some blistering noted. Painting will probably be necessary in 2 to 4 years (1975 to 1977)
- (6) Bearings - Generally satisfactory. Movable bearing at center pier is apparently frozen. No physical reason apparent, however dam tender will loosen nut on anchor bar which extends through slot in bearing pad.
- (7) Guard Rail and Fencing - No problems noted
- (8) Bridge Movement - Minor movement has been noted during instrumentation surveys

(b) Intake Tower

(1) Structural

- (a) Concrete Surfaces - No deficiencies noted
- (b) Concrete Cracks - No additional cracks noted since previous inspection. Top deck slab continues to leak. Recommend trial use of fiberglass cloth-epoxy combination for repair
- (c) Leakage - Leakage at form tie locations and joints below water line appears less than previously noted. Calcite formation and dehumidification system credited for improvement

(2) Equipment

- (a) Service Gates and Hoists - No deficiencies noted.
- (b) Emergency Gates and Hoists - No deficiencies noted.
- (c) Water Quality Control Gates and Hoists - Control gate leaks around stem seal at certain gate settings. Deficiency appears to involve machining of gate stem.
- (d) Engine Generator - Hydraulic starter for emergency engine generator is difficult to re-prime should the diesel engine fail to start. Re-priming by hand crank to required 2000 psi takes about 30 minutes. The problem will be investigated to determine if electrical battery-powered system would prove more dependable.
- (e) Sluice Gates & Hoist - No deficiencies noted.
- (f) Elevator - No malfunctions noted. Permanent repairs have been completed since last periodic inspection. Maintenance contractor keeping elevator in working order.
- (g) Dehumidifier - fabrication of system being completed. System is functioning but work had not been finally accepted at the time of inspection.
- (h) Sump pumps & By-pass Drain - No problems noted.
- (i) Electrical - Most deficiencies noted in third periodic inspection have been repaired by District electrician. A few receptacles are still to be reset.

(3) Conduit and Stilling Basin

a) Conduit

- (1) Concrete Surface - No change noted since previous inspection
- (2) Concrete Cracks - No change noted since previous inspection
- (3) Leakage - Construction joint at station 11 + 50 continues to leak as noted in second and third periodic inspections
- (4) Joints - No major problems noted. Spalling at construction joints at conduit station 0 + 24 and north chamber station 0 + 34. Spalls appear to be result of patch failures.
- (5) Drains - No deficiencies noted

(b) Stilling Basin

- (1) Concrete Surfaces - No changes noted since previous survey

- 2) Concrete Cracks - No changes noted since previous survey
- 3) Leakage - None noted
- 4) Joints - No deficiencies noted
- 5) Seams - Weep holes appear to be functioning properly
- 6) Outlet Channel - Outlet channel side slopes have suffered erosion on both banks due to extremely high releases and the conduit rate rating and prototype testing performed by WFS during the spring of 1973. Installation of eroded areas in weathered shale by riprap placement was recommended. Outlet channel earth slopes should be seeded.

Some seepage along left side of outlet channel was noted. This seepage emerges from rock and appears to be no problem at present.

#### (4) Embankment

- (a) Surface Cracks - None noted
- (b) Abutment and Embankment Junctions - No problems noted
- (c) Vertical and Horizontal Alignment - Satisfactory. Analysis of instrumentation readings should continue at present schedule with attention to settlement at SI-5
- (d) Unusual Movement or Cracking at or beyond toe - None noted
- (e) Unusual Through Embankment or Downstream Seepage - NAD personnel concurred in limiting the study of seepage to analysis of embankment through-seepage. Preliminary seepage analysis indicates observed seepage is not abnormal for this embankment and pool height. NAD recommended continued monitoring of the weir system and that seepage noted coming off the steep left abutment be observed and any deviations from present patterns be noted. Project maintenance forces will repair Weir No. 1 which was allowing a small amount of water to bypass its left side.
- (f) Sloughing or Erosion of Embankment and Abutment Slopes - Minor erosion along the right abutment - embankment contact zone on the upstream side of the embankment was noted as previously reported in the 2nd Periodic Inspection. Recommend project forces reshape ditch or provide check dams to prevent undermining riprap in this area.
- (g) Movement of Structural Features in Embankment - Small northward horizontal movement was recorded on the tower bridge alignment survey at the eastern bridge slabs nearest the tower. Continued observation to determine if movement is active was recommended. Present amount of movement (0.045 foot maximum) presents no danger to the structure
- (h) Riprap Failure - Major Displacement - None noted

Spillway

a. Bridge

- (1) Concrete Surfaces - No deficiencies noted
- (2) Concrete Cracks - None noted
- (3) Expansion Joints - Joint sealant showing deterioration. Replacement not required at this time, however monitoring is recommended.
- (4) Drainage System - No deficiencies noted
- (5) Structural Steel - No deficiencies noted. Paint beginning to show signs of aging, however repainting is not recommended at this time
- (6) Bearings - No deficiencies noted
- (7) Guard Rails - No problems noted. Nuts on railing anchor bolts have been tightened since third periodic inspection
- (8) Bridge Movement - No evidence of movement noted. Monumentation of bridge for vertical and horizontal movement should be completed. Survey measurements to be taken on three months interval compatible with existing survey schedule. Vertical alignment to be established on northward pier to determine reason for joint material extrusion along south edge of pier and spillway slab contact

b. Chute and Gravity Walls

- (1) Concrete Surfaces - No significant change noted since previous inspection
- (2) Concrete Cracks - No change noted since original crack survey performed subsequent to second periodic inspection
- (3) Expansion Joints - Joint along left side of north spillway bridge pier at spillway chute slab is very tight extruding the joint filler material. The joint space on the right side of this pier shows a corresponding open space so that the joint material no longer fills the entire space. The reason is not readily apparent but has been noted on all previous inspections. The pier will be monumented to determine whether any movement is taking place in the bridge.
- (4) Drainage System - No problems noted. Screens have been installed to prevent entrance of small burrowing animals into underdrain system as recommended in previous inspections
- (5) Leakage - None noted

2. Wet areas located at upstream end of spillway were observed. Recommend drainage of this area to shallow ditch to be investigated.
3. All personnel recommended that construction files be researched for spillway slope configuration immediately after excavation and for comparison with present slopes. Available photographs should be utilized.

#### Delta Area

- a. Erosion and Irrigation - As mentioned in paragraph 3 above, therefore, erosion of the outlet channel has taken place and corrective action is recommended. The installation of drainage pipe from Delta Porrow Area to Saw Mill Run has been completed and is performing satisfactorily.
- b. Surface Cracks - None noted
- c. Dam - Monitoring to continue and aforementioned repairs to weir No. 1 will be accomplished by operating personnel.
- d. Sewage Treatment Plant - Condition good. Plant operator explained his intent to change trickling filter outlets (reversal of 1st and 3rd outlet sizings) to better distribute the effluent onto the filter material. Change was agreed to by NAB and NAD personnel.

#### Highway Area

- a. Condition of Reservoir Slopes - No problems noted except for small amount of erosion in several minor areas. Dam tender will continue annual inspections of the shoreline to locate and record eroded areas.
- b. Condition of Highway Embankments and Riprap - No deficiencies noted
- c. Concrete Drainage Ditches - Good condition. No problems noted
- d. Highway Bridges - L.R. 13015 bridge approach shoulders on left side are badly eroded. Since this is a state road, the maintenance forces responsible for the work will be contacted informally and made aware of the potentially dangerous condition should the erosion continue. Bridges along the relocated highways are in good condition.
- e. Recreation Areas. No problems noted. No recurrence of problems noted during the third periodic inspection with cars sliding into water at boat launching ramp while attempting to off or on load boats. Boat launching ramps are being swept clean of loose gravel which may have contributed to former problems.

Periodic corrective measures are also undertaken by District personnel to alleviate problem areas or investigate problem solutions. The inspection comments and corrective measures undertaken or problems investigated are listed below:

a. Periodic inspection No. 1

Page 4. "The main and emergency junctions: erosion noted along both downstream side wall rear junctions on the right abutment. The main and emergency junction should be directed from the toe and problem will be addressed to reduce erosion." The last of which personnel, as a portion of their maintenance duties, are filling the drainage ditch and regrading the junction area upstream of the embankment to provide drainage away from the abutment toe. Subsequent inspections by District office personnel determined that the filling and regrading is alleviating the erosion problem.

Page 4. "A small seepage embankment on downstream slope: Small springs were observed along left abutment, downstream of dam. District will monitor the flow by observation and/or installation of a weir." The initial weir was installed on 14 August 1971, immediately after Periodic Inspection No. 1, and monitoring of the seepage was begun. A more detailed explanation of actions taken relative to the downstream seepage is contained in paragraph 8 of this report.

Page 5. "Water passages including drains: Pressure cell cover, located in the floor of water quality control chute was missing and will be replaced by District forces. See paragraph 7c. (6).

Page 6. "A ditch, which runs from the downstream toe to 25 feet in depth with overhanging trees, presents a safety hazard to the public." A contract was awarded to George E. Lynn, Incorporated, on 27 June 1972 for erosion control at this ditch. Approximately 180 feet of 48-inch diameter reinforced concrete pipe and 200 feet of 36-inch diameter reinforced concrete pipe were installed and backfilled in the erosion area. The contract for this work was completed on 15 April 1973.

(b) Periodic Inspection No. 3 (Section 5 of this report)

1. Paragraph 5 (1)(c)(3). "Water quality control gates and floats - Gate does not close completely having an opening of 0.4 inches in the closed position. Study of the problem and possible remedial treatment has been initiated." A study of this problem indicates the slight opening does not affect the safety or operation of the project. In addition, the control gate can be closed manually should complete cutoff of this gate required.
2. Paragraph 5 (1)(c)(4). "Sluice gates and floats - The number 1 sluice gate has a bent stem and cracked casing and indicators are loose. The problems are under study and the stem and casing will be replaced and indicators repaired." The bent stem and cracked casing were replaced during the spring of 1973. The remaining stems were checked for adjustment and adequate performance.
3. Paragraph 5 (1)(c)(5). "Elevator - The elevator was not operational at the time of the inspection. Inspection and repair of the system was accomplished by factory representatives during the week of 17 September 1973. Shorts in the power cable and corrosion of relay contacts due to high humidity in the tower are the primary causes of these operational problems. A study of the humidity problem and possible corrective measures has been initiated." A contract for dehumidification of the intake tower was awarded on 23 May 1973 and, although not completed the system was in operation at the time of the fourth periodic inspection.
4. Paragraph 5 (1)(c)(7). "Electrical (General) - water is present in electrical conduits and boxes at lower elevations. Surface mounting of outlets to prevent trapping of water and repair of one dead portable heater socket at Fl. 54" was recommended." The lower elevation wiring has been replaced completely at the lower tower levels. The outlets and mountings have been modified to insure free drainage of water from the conduits.
5. Paragraph 5 (1)(c)(8). "General - providing for heat in the lower levels of the tower is a problem. A study of this problem and possible corrective measures has been initiated." The dehumidification contract mentioned in (3) above also included complete revision of the heating system to provide adequate tower heating at the lower levels.

Paragraph 5 (2)(a)(5). "Water passages including drains - cover plate missing at pressure cell location T-6 in water quality control outlet; cover plate will be replaced after completion of repairs to water quality control gate stem." Pressure cell cover plate was replaced in spring of 1973 while testing the conduit for prototype comparison with WED model.

Paragraph 5 (4)(a)(7). "Guard rails - many nuts holding guard rail to bridge postpet are not tight against the railing base; nuts should be tightened to required torque." The dam operating personnel, as part of their maintenance duties, re-tightened the loose anchor bolt nuts.

Paragraph 5 (4)(b)(4). "Drainage system - general condition is good. Inspection team recommended installation of screens at outlet end of collector pipes to prevent entry of animals and possible blockage." The screens were installed by dam operating personnel as part of their normal maintenance duties. Future weep holes design for other projects should include installation of screens of nondeteriorating material. The screens should be removable to allow weep hole cleanup should this become necessary.

Paragraph 5 (4)(c)(1). "Spillway side slope - erosion noted along right side of spillway cut upstream of chute and repair of eroded section and installation of slope pipe to carry flow was recommended." The erosion was being caused by a low area (3 to 4 feet) in the right side top-of-cut spillway drainage ditch. The dam tender has regraded the drainage ditch to provide a continuous ditch grade, thus preventing the water runoff over the spillway side slope. The side slope erosion area has been reseeded for bank stabilization.

Paragraph 5 (4)(c)(2). "Miscellaneous - In answer to head dam operator's question, team recommended cutting saplings which are growing in upstream section of spillway before additional growth makes removal difficult." Dam operating personnel have removed or cut the saplings.

(11) Paragraph 5 (5)(c). "Weirs - Team recommended reinstallation of weir in ditch to right of stilling basin and installation of weir at upstream end of pool to determine quantity of seepage from zone noted at left abutment and downstream toe junction." The right abutment weir was reinstalled



and upstream weir near the left abutment was installed by project operating personnel. A more detailed explanation of the actions taken is contained in the Seepage Study, section 6 of this report.

## 7. SEEPAGE STUDY:

### a. History:

1. Embankment Construction. Construction records and recollections of design and construction personnel at the Melitzville project indicate the existence of small springs on the steep left abutment, downstream of the embankment prior to embankment construction. To provide drainage for runoff, a portion of the original creek channel downstream of the embankment was left open whereas the remainder of the channel was used as a spoil area for deposition of random material used for the downstream cofferdam. This open portion of the original stream channel contained the flow emerging from downstream abutment springs prior to impoundment however it is not known whether the springs were present in dry periods.
- (2) First Periodic Inspection. The first periodic inspection team noted the ponding of water in the original stream channel, however no seepage was evident in the immediate vicinity of the embankment toe. The first periodic inspection took place prior to impoundment and, therefore the ponding of water was attributed to the stream grade and rainfall runoff. No embankment seepage was noted during the initial inspection.
- (3) Second Periodic Inspection. During July 1971, the second periodic inspection team noted seepage emerging from the embankment in the vicinity of the original stream channel. Pool level was elevation 602, twenty-six feet below normal operating pool. The suggestion was made that a weir be installed to measure the flow, and establish its relation to reservoir elevation. Weir 1 was installed in the old stream channel and readings began in August 1971.
- (4) December 1971. During December of 1971 the head dam operator noted a continuous seepage in the vicinity of the right abutment and embankment junction immediately right of the stilling basin. This area has shown intermittent flow during periods of rainfall (see photographs 3 and 3-A of Periodic Inspection Report No. 2), however the flow appeared continuous at this time.

Third Periodic Inspection. The third inspection team (14 September 1972) suggested two additional weirs be installed and requested a study of the seepage. Weir 2 was installed near the embankment toe and left abutment intersection to measure the seepage at this point and weir 3 was installed to the right of the stilling basin to monitor the seepage noticed during September 1971.

Fourth Periodic Inspection. The fourth inspection team (23 August 1973) reviewed a preliminary seepage analysis and concurred in the scope of study. The team inspected the weirs and seepage area and recommended seepage around weir no. 1 be corrected and the springs on the left abutment be observed. The inspection team also noted small seeps not being monitored by the weir system in the rock at the left side of the outlet works channel. Monitoring of this seepage is not practicable because of the scattered locations and irregularity of the rock.

b. Weir Reading Results

1. Weir No. 1. Weir No. 1, is located in the original stream channel approximately 400 feet downstream of the embankment toe along the steep left abutment. Weir readings obtained during the first two months of monitoring indicated a direct comparison between rainfall and weir discharge and a base flow during periods of minimal precipitation. As reservoir impoundment progressed from elevation 605 to elevation 620, the base flow recorded in weir no. 1 increased to 0.4 cfs (180 gal/min) where the base flow appears to have stabilized. Individual heavy rainfalls have produced recorded discharges as high as 2.0 cfs, the maximum recordable by this portable weir.
2. Weir No. 2. Weir No. 2, is located near the intersection of the left abutment and embankment toe. Readings from this weir indicate a direct correlation with rainfall runoff and a base discharge of approximately 0.2 cfs (90 gal/min).
3. Weir No. 3. Weir No. 3, is located on the right abutment-embankment interface to the right of the stilling basin. This weir, which fluctuates less with rainfall than either weir 1 or weir 2, appears to hold a base flow of approximately 0.025 cfs (10 gal/min). Weir monitoring results, plotted along with rainfall and pool elevations, for the three weirs are shown on plate 18.

(4) Discussion. Weir readings indicate that the base flows in the three weirs have stabilized since the reservoir normal operating level was reached. The base flow is taken as a measurement of seepage and the lack of increase in the base flow after reaching full pool indicates a safe controlled flow rate. Sources of the base flow (0.4 cfs, 180 gpm) measured at Weir 1 included embankment through-seepage and side-seepage through the rock foundation in the valley, left abutment and adjacent portion of the right abutment. All of this would be collected in the old stream channel and flow to this weir. An estimate of the embankment seepage is made in the following paragraphs for comparison with the flow at weir 1. In this estimate the limit of the embankment portion on the right abutment contributing flow to Weir 1, as indicated by the true slope of the base portion of the internal drain, is Station 9 + 000. Seepage originating to the right (north) of this station is either dissipated into the surried valley in that area or, if there is longitudinal flow in the rockfill zone, intercepted at the conduit and discharged through rock backfill into the outlet channel.

(5) Computation of Embankment Through-Seepage Sta 9 + 000 to 10 + 000.

a) Embankment Permeability and Flow Nets. The seepage computations are based on flow nets prepared for two limiting assumptions as to effective size and permeability of the impervious barrier. This was done to consider the effect of variable permeability in the random zone adjacent to the core which ranged from material with permeability characteristics the same as the core to material with significantly higher permeability. Accordingly, flow nets were drawn assuming in one case an impervious zone the same as the core and, in a second case, a larger impervious zone which includes the core, random fill between the core and drainage zone, and a portion of the adjacent random fill on the upstream side.

b) Coefficient of Permeability and Seepage Quantity. From tests during the design phase and observation of materials actually placed the permeability of the core is considered to range from  $1 \times 10^{-4}$  to  $1 \times 10^{-5}$  cm/sec. Computations using these values are shown on the flow nets. The resulting four flow rates are 4, 11, 40 and 150 gpm; from which it is likely (95% chance by statistical methods) that the embankment through-seepage is between 25 and 125 gpm. Thus 1/3 or more of the 180 gpm

base flow at Weir 1 apparently originates from other sources. It is reasonable to attribute this portion to the foundation rock since seepage can be seen emerging from rock in the outlet channel area and rather large grout takes occurred in two holes during curtain grouting at the left abutment. The vertical cracks in rock in the left abutment cutoff trench area (oriented approximately parallel to centerline and treated with a special mortar application) may also be a factor in this flow.

Piezometer Readings. No unusual conditions are shown by the embankment and foundation piezometers. The internal drain from these data appears to be functioning as designed and maintaining a satisfactory drained state in the downstream portion of the embankment.

Evaluation. The weir readings and stabilization of the base flow after reaching full pool show that the seepage is, to the present, a small and controlled discharge which, from embankment seepage computations and other indications, originates primarily from the rock foundation. Since the flow is small and stabilized and there is no visual or instrumental evidence of any harmful effects, the seepage is not considered to represent any serious problem. Monitoring of the weir flows will continue.

#### 9. RESULTS OF INSTRUMENTATION

The results of readings on the existing instrumentation during the construction period and during impoundment to elevation 612 were presented in previous periodic inspection reports. A brief discussion of instrumentation elevation 628 and instrumentation results during post impoundment prior to the fourth periodic inspection follows:

- a. Piezometers. During the final impoundment stage, as had been experienced throughout the reservoir filling, the piezometers reacted in accordance with their relative position in the embankment. General piezometric patterns established during the initial reservoir filling continued during the final filling from elevation 612 to elevation 628. Those piezometers located upstream of the impervious core rose at the same rate, or slightly slower, than the reservoir rise. The piezometers located in the impervious core material indicated a rise in water level. However, the rise occurred at a much slower rate than the reservoir rise. The pressure cells located downstream of the impervious core indicated minor rises in pore pressure or no pore pressure readings.

After normal operating pool elevation has been achieved, the piezometer and pressure cell readings stabilized at relatively constant values. Most upstream piezometers (PZE 77-1, PZE 95-1 and PPF 98-1) stabilized at or near the reservoir operating elevation 626. Two additional upstream piezometers, PZH 86-1 and PPF 92-1, indicated minor discrepancies from the general behavioral patterns established under normal pool elevation. Possible reasons for the non-typical behavior exhibited by these piezometers are presented in the second periodic inspection report.

Impervious core piezometers (PZC 77-2, PZC 95-3 and PZC 98-2) indicate piezometric water levels from 8 to 37 feet below pool elevation as of August 1973. The impervious core piezometer levels appear to relate to embankment width and hence length of seepage path to the piezometer tip location.

The downstream pressure cells have shown rises in water pressure readings from 0 to 11 feet. The maximum 11 foot rise, recorded in pressure cell PPF 98-3, is well below the water level assumed during steady seepage design calculations and appears to be a normal condition.

Two downstream pressure cells have become inoperative since their installation into the embankment and contributed little information prior to malfunction. The reason for the malfunctions are not apparent at this time. District personnel are presently planning to replace the inoperative pressure cells with Casagrande-type open piezometers since these instruments appear to provide more serviceability and reliability.

With the exception of the two inoperative pressure cells the piezometer instrumentation appears to be performing satisfactorily. There are no important deviations from theoretically anticipated behavior and the internal drain in the downstream slope of the embankment appears to be functioning as planned. Replacement of inoperative pressure cells will be made as funds become available.

- b. Slope and Settlement Indicators. The slope and settlement indicators were established as embankment construction progressed to measure movements in three directions. Alignment of the instruments permit measurement parallel to the dam centerline (north-south), perpendicular to the dam centerline (east-west) and horizontal settlements within any portion of the embankment height. A summarization of readings was first presented in Design Memorandum No. 17 entitled Instrumentation, and updated in the first and second periodic inspection reports. The summarized readings, current as of 20 March 1973 are as follows:

INSTALLATION	W. OF FILL TO BOTTOM OF CHANNEL	MAXIMUM SETTLEMENT AND DATE 3-20-73	NORTH- SOUTH	DEFLECTION	EAST- WEST	DEFLECTION
VIF 92-2 (St. Abut.)	100'	1.00' 600.11-611.01'	North	3.14" 2/70 2.25" 3/73	East	2.32" 4/71 2.41" 3/73
VIF 95-2 (Closure)	100'	1.24' 604.73-609.72'	South	-3.04" 9/70 -2.89" 3/73	East	3.80" 1/70 2.18" 3/73
VIF 98-5 (Left Abut.)	115'	1.24' 608.79-613.79'	North	1.73" 11/71 1.47" 3/73	East	3.58" 8/71 3.17" 3/73

As expected, the majority of settlement to date occurred during construction of the embankment; amounting to 76%, 83%, and 78% in installations VIF 92-2, 95-2 and 98-5 respectively. The embankment zone at which maximum settlement has occurred correlates closely in the three instruments, as discussed in the second inspection report. The installations 92-2 and 95-2 have indicated maximum settlement changes since the second periodic inspection report of 0.02 and 0.05 feet, respectively, whereas instrument 98-5 has shown no maximum settlement increase.

All three inclinometers indicated an initial upstream (easterly) movement prior to impoundment and a downstream (westerly) trend during reservoir filling. The maximum movement in the east-west direction was recorded in instrument 92-2 during April of 1971 and the maximum movement in the north-south direction was recorded in 92-2 during February of 1970. During the period between the second periodic inspection (recordings of 29 September 1971) and the fourth periodic inspection (recordings of 20 March 1973), very little movement has occurred in the inclinometers. These movements amount to less than 0.20 inches in the east-west direction (VIF 98-5) and less than 0.36 inches in the north-south direction (VIF 95-2) during the 17 month period.

3. Surface Settlement Pipes. Surface settlement readings, which are shown in Table 1 hereafter, were first presented in the second periodic inspection report. During the recording period from 5 October 1971 to 3 July 1973, the settlement indicated negligible movement in the horizontal (less than 0.10 feet) and vertical (less than 0.05 feet) with the exception of instruments SP-5 and SP-7 which exceeded these limits in the horizontal direction.

As presented in the second periodic inspection report, it was thought that a general pattern of behavior was being experienced in the vicinity of the temporary end-fill zone of the embankment: Station 8+000 to Station 9+400. This theory was based on settlement readings on pipes SP-4, SP-5 and SP-6 which indicated the three largest settlement readings of the seventeen settlement pipes. This trend remains, but is now apparently affecting only SP-5 where the settlement is 0.49 feet.

General behavioral patterns established by the settlement pipes since their initial installation, neglecting SP-5, indicates less than 1/2 inches horizontal and less than 1 inch vertical movement in the 2-3 year recording period.

4. Tower Bridge. A study of the tower bridge movement in both the horizontal and vertical direction has been undertaken since August of 1971. The readings are obtained on a three-month schedule by survey branch personnel as the settlement pipe and inclinometer elevations are obtained. The survey points are punch marks located in the fixed plate and movable bar at each plate expansion joint of the bridge roadway. The points are numbered from one to ten beginning at the bridge-embankment abutment and proceeding eastward.

The results of the tower bridge movement are presented hereafter in Table 2. Results to date indicate very little movement has taken place at the expansion joint located above the middle pier of the three-span bridge (survey points 1 and 2). The fourth periodic inspection team inspected the expansion bearings at this location but could find no reason for the lack of movement. The dam operator was instructed to loosen the anchor bolt nut at the slotted expansion bearing to determine if the nut was preventing movement.

Vertical offsets measured along the bridge center line indicate a small eastward movement at pier number 3 (survey points 7 and 8) amounting to 0.04 feet. Specific reasons for this movement are not apparent, however the lack of movement at the pier number 2 expansion joint may be a contributing factor.

TABLE 1  
SURFACE SETTLEMENT DATA

SETTLEMENT PIPE & OFFSETS & ELEVATIONS

1 INSTRUMENT NUMBER	2 STATION	3 HEIGHT OF FILL	4 INITIAL SURVEY DATE	5 INITIAL E OFFSET	6 E OFFSET (5 Oct 71)	7 DIFF 5-6	8 INITIAL ELEVATION	9 ELEVATION (5 OCT 71)	10 DIFF 8-9
SP-1	6+901.03	27	9 July 70	14.49	14.44	-.05	672.04	672.03	-.01
SP-2	7+401.03	44	9 July 70	14.50	14.44	-.06	672.04	672.02	-.02
SP-3	7+901.42	72	9 July 70	14.50	14.54	+.04	672.06	671.98	-.08
SP-4	8+401.48	74	9 July 70	14.41	14.44	+.03	672.03	671.87	-.16
SP-5	8+901.15	91	9 July 70	14.40	14.54	+.14	672.04	671.55	-.49
SP-6	9+401.43	166	9 July 70	14.58	14.54	-.04	672.02	671.82	-.20
LBS-1	9+580.0	172	18 Dec 70	14.44	14.48	+.04	671.68	671.49	-.19
LBS-2	9+630.0	172	18 Dec 70	14.55	14.51	-.04	672.00	671.85	-.15
LBS-3	9+680.0	172	18 Dec 70	14.58	14.54	-.04	672.04	671.89	-.15
LBS-4	9+730.0	172	18 Dec 70	14.53	14.44	-.09	672.05	671.90	-.15
LBS-5	9+780.0	146	18 Dec 70	14.79	14.74	-.05	672.04	671.90	-.14
LBS-6	9+830.0	118	18 Dec 70	14.74	14.73	-.01	671.97	671.79	-.18
LBS-7	9+880.0	116	18 Dec 70	14.55	14.53	-.02	671.86	671.72	-.14
SP-7	9+901.71	116	9 July 70	14.51	14.52	+.01	672.03	671.87	-.16
LBS-8	9+930.0	65	18 Dec 70	14.38	14.37	-.01	672.12	672.01	-.11
LBS-9	9+980.0	16	18 Dec 70	14.53	14.55	+.02	672.32	672.24	-.08
LBS-10	10+030.0	0	14 & 27 May 71	13.67	13.66	-.01	688.10	688.08	-.02

\* UPSTREAM POSITIVE (+); DOWNSTREAM NEGATIVE (-)



TABLE 2

## TOWER BRIDGE MOVEMENT STUDY

PELKEYVILLE LAKE

MARK NUMBER	FUNCH MARK ELEVATIONS								TOWER BRIDGE CENTRILINE OFFSET - N (+)				
	DATE								DATE				
	8/13/71	7/12/72	9/13/72	12/8/72	3/20/73	7/3/73	8/12/71	7/12/72	9/13/72	12/8/72	3/21/73	7/3/73	
10	672.087	672.09	672.09	672.09	672.09	672.09	-	-	-	-	-	-	-
9	672.078	672.07	672.07	672.06	672.07	672.07	0.000	0.000	0.000	0.000	0.005	0.000	0.000
8	672.097	672.10	672.10	672.11	672.12	672.11	0.000	0.018	0.025	0.045	0.040	0.043	0.043
7	672.081	672.08	672.09	672.09	672.10	672.09	0.000	0.015	0.025	0.040	0.045	0.042	0.042
6	672.091	672.08	672.08	672.11	672.10	672.08	0.000	0.000	0.005	0.010	0.005	0.007	0.007
5	672.073	672.07	672.07	672.09	672.08	672.07	0.000	0.000	0.010	0.010	0.005	0.007	0.007
4	672.047	672.06	672.06	672.08	672.08	672.06	0.000	0.000	0.010	0.010	0.008	0.010	0.010
3	672.045	672.06	672.05	672.08	672.07	672.06	0.000	0.000	0.010	0.010	0.007	0.008	0.008
2	671.750	671.71	671.71	671.73	671.72	671.69	0.000	0.000	0.000	0.005	0.000	0.000	0.000
1	671.724	671.69	671.69	671.71	671.70	671.67	-	-	-	-	-	-	-

TABLE 2 (Continued)  
 LOWER BRIDGE MOISTURE STUDY  
 BRIDGEVILLE LAKE

MARK NUMBER	DISTANCE BETWEEN SPAN FLITCH MARKS					
	DATE					
	5/12/71	7/12/72	9/13/72	12/8/72	3/21/73	7/3/73
10	0.500	0.495	0.505	0.500	0.498	0.498
9						
8						
7	0.496	0.490	0.515	0.565	0.548	0.508
6						
5	0.500	0.495	0.510	0.498	0.500	0.498
4						
3	0.500	0.490	0.520	0.568	0.550	0.505
2						
1	0.500	0.510	0.525	0.550	0.550	0.510

Additional elevations taken at the bridge punch marks indicate little or no movement except at the bridge-embankment abutment which has settled 0.05 feet in the two-year observation period.

No problems have been indicated by the movement records. The District will continue to monitor this feature of the project and evaluate the movements.

#### 1.1. ENVIRONMENTAL QUALITY CONTROL EQUIPMENT

- a. System Operation. A description of the environmental quality control equipment presently installed at Beltzville Dam and a summary of the difficulties experienced to date with this equipment is presented herein as information to other Districts planning to install similar equipment in future projects.

The system is unique in that it records reservoir level, downstream creek level, dissolved oxygen, water temperature, acidity or alkalinity, and conductivity from eight water quality control gate levels on a rotational basis. The water from eight different reservoir sample levels flows through embedded pipes either to a flume or to the water sample tank that contains the dissolved oxygen, temperature, PH, and conductivity analyzers. The constant flowing minimizes the effect of tower wall temperature on the measured parameters. The tower wall temperature effect is checked by thermocouples at each of the eight sample inlet locations and the sample tank.

solenoid valves are used to direct water from the selected water level inlet location to the sample tank. The levels are automatically, sequentially, selected on a manually variable timed interval and the data is recorded on an outlet typewriter and on punched paper tape. Any inlet level above reservoir level is automatically locked out of the sampling cycle and any inlet level can be locked out manually.

The perfected process could provide scientific data on reservoir seasonal changes and provide selective withdrawal information necessary to meet future water quality criteria downstream of the project.

- b. Installation and Operational Problems. The contract for installation of the environmental quality control monitoring equipment was awarded to Honeywell, Incorporated in August of 1970 and was specified for completion by 31 May 1971. The contract was awarded as a supply contract and, as such, provides for no liquidated damages.

The initial shop drawings were submitted by the contractor three months prior to the scheduled completion date and the final shop drawings were submitted five months after the scheduled completion date. There is no monitoring system presently in production to provide the information specified for Beltzville and, therefore, the system had to be fabricated from component units currently in production and modified to provide the required monitoring.

The greatest single problem source has been the typewriter paper unit used for output data logging. The original unit produced by the contractor was rejected as incompatible with the output capacity requirements of the specifications. The automatic typewriter is required to reproduce the sensor output values on typed log sheets and the digital recording system to convert the analog signals from the individual parameter analyzers to digital format and reproduce them on an 8-channel punched paper tape. The "Hriden" unit that was finally approved had a two month delivery time and required modifications for compatibility with other components of the system. The unit was shipped to a subcontractor for modification and was damaged in shipping, thereby resulting in a further delay. The unit was connected to the system, checked during shop tests, and found to be producing about 75 percent accurate data. The problem has continued and the system had not been finally accepted as of September 1973.

The specification required the output devices to operate in three modes; type and punch concurrently, type only, and punch only. The contractor apparently overlooked the punch only mode and the machine required modification to incorporate this feature.

In addition to the major problem of data output and general unreliability of data, several lesser problems have been experienced with the system and its installation. Some of the lesser problems are noted below:

- (1) The water jet for the dissolved oxygen analyzer was omitted from the sample tank originally. The omission had a very adverse affect on the dissolved oxygen response time and the water jet has since been installed.
- (2) The electronic module for the conductivity analyzer was damaged, apparently by a lightning surge and has been replaced. The dam operator reports the system is highly sensitive to lightning and power surges.

- (3) The data transmission line from the downstream stream gaging station, which is leased from Bell Telephone Company, broke and a temporary transmission line was installed.
- (4) Two thermocouples for installation at the sample inlets had faulty water tight seals and were repaired. Two additional thermocouples were delayed in delivery to the site.
- (5) Two conduits for thermocouple installation were blocked and had to be abandoned. These conduits were installed under the embankment and outlet works construction contract. Attempts to clear the conduits added to the delays in completion.

## 11. SUMMARY

The primary construction contract for the Beltzville Lake project was completed on 10 July 1970 at which time the project was considered fully operational for flood control purposes.

The initial periodic inspection performed under the purview of FH 1110-1-100 was conducted on 22 July 1970, six months after topping-out of the embankment and prior to intentional impoundment. As a result of that inspection the installation of ten additional surface settlement pipes was recommended and adopted.

In accordance with the inspection recommended in Design Memorandum No. 17, Instrumentation, and Periodic Report No. 1 for Beltzville Lake, the second periodic inspection was conducted on 22 July 1971, approximately six months after initiation of impoundment. Pool elevation at the time of the inspection was 602, twenty-six feet below water supply pool. The second periodic inspection team suggested a crack survey be performed on the spill way slab, a crack survey as performed after the initial inspection be duplicated to note changes, a weir be installed to measure seepage downstream of the embankment, and several erosion problems and minor deficiencies be corrected.

The third periodic inspection was conducted on 14 and 15 September 1971 due to a postponement generated by tropical storm "Agnes". The major area of concern to the third inspection party was seepage located downstream of the embankment. Installation of two additional weirs and a study of the seepage were requested.

The fourth periodic inspection was performed on 23-24 August 1972. Since the third periodic inspection report had not been submitted due to the emergency workload and subsequent manpower loss caused by "Agnes", it was requested that the third and fourth inspections be combined under one report. The major areas of concern to the fourth inspection party were,

observation and continued monitoring of seepage, correction of minor erosion problems, and monitoring of the instrumentation. The weir records show no increases in base flows thus indicating a stabilized seepage flow which is of minimal volume and does not represent a major concern. Monitoring the weir flows will continue.

The instrumentation installed to date appears to be adequately measuring the performance of the dam during the operational phase. Two pressure cells, which are presently inoperative, will be replaced by open-type piezometers. The spillway service bridge will be monitored in accordance with the tower bridge instrumentation program.

The overall condition of the project is considered excellent. Minor remedial work, as necessary, will be accomplished by routine maintenance and as funds become available on more significant items. The fifth recommended periodic inspection is presently scheduled for August 1974.





CORPS OF ENGINEERS










CORPS OF ENGINEERS



1970



LEGEND

- ▲ PRESSURE CELL W/ALUM
- VERTICAL PENETRATION INST
- PIEZOMETER CASAGRANDE TYPE
- RIVER - POHOPOCO CREEK
- PZC 101.3
- PZC 101.1
- PZC 101.5
- PZC 101.3
- PPF 101.1
- PPF 101.4


LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA

BELTZVILLE LAKE

PIEZOMETER DATA  
1969-1970

CORPS OF ENGINEERS


1971




NOTES

Piezometer No 95-4 became


1972




CORPS OF ENGINEERS




CORPS OF ENGINEERS





LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA  
BELTZVILLE LAKE


PIEZOMETER DATA  
1973-1974



#### LEGEND

- ▲ Pressure cell
- Vertical inclination inst.
- Piezometer
- PZC Piezometer - Cutoff trench
- PZE Piezometer - Embankment
- PZF Piezometer - Foundation
- VIF Vertical inclination instrument - Foundation
- PFE Pressure cell - Embankment
- PFF Pressure cell - Foundation





STATION 7 + 770

Scale in Feet

0 20 40

cell

inclination inst

- Cutoff trench

- Embankment

- Foundation

incl instrument - Foundation



cell Embankment


cell Foundation

REVISIONS			
STN.	DESCRIPTION	DATE	APPD

LEHIGH RIVER BASIN  
 BELTZVILLE LAKE  
 POHOPOCO CREEK, PENNSYLVANIA


INSTRUMENTATION LINE  
 STATION 7+770





200  
AXIS STATION 8 + 600



Scale in Feet  
25 0 25 50



200  
AXIS STATION 9 + 280


Scale in Feet  
40 0 40 80

REVISIONS			
REV.	DESCRIPTION	DATE	APP.



LEHIGH RIVER BASIN  
 BELTZVILLE LAKE  
 POHOPOCO CREEK, PENNSYLVANIA

INSTRUMENTATION LINE  
 STATION 8+600 @ STATION 9+280




AXIS STATE

Scale in

0

40






AXIS STATE

Scale in

0


30









CORPS OF ENGINEERS





U.S. ARMY




LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE

SURFACE SETTLEMENT PIPE PLAN


PLATE 8

1969

SETTLEMENT  
1 INCH = 0.4'



1970




NOTE

564 30 (10) = INITIALLY INSTALLED BOTTOM  
ELEVATION FOR CASING #10

LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF - 92 - 2 1969 - 1970


CORPS OF ENGINEERS



NOTE

Initial datum for settlement of section casing (2)

Measured settlement in section casing (2)




LEHIGH RIVER BASIN  
 POHOPOCO CREEK, PA.  
 BELTZVILLE LAKE  
 SUBSURFACE SETTLEMENT DATA  
 VIF - 92 - 2 1971 - 1972

CORPS OF ENGINEERS

1973

SETTLEMENT (SCALE 1"=10.40')



NOTE


- Initial datum for settlement of section casing (2)

(2) A small diagram showing a cross-section of a casing with a datum point labeled (2).

< Measured settlement in section casing (2)




1974




LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF - 92 - 2 1973-1974

SEIEMENT  
SCALE 1" = 0.40'




NOTE 41  
FI



NOTE 49915 (2) - INITIALLY INSTALLED BOTTOM  
ELEVATION FOR POINT 11.


LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF - 95 - 2 1969 - 1970

# CORPS OF ENGINEERS




NOTE:

Initial datum for settlement of section casing ②



Measured settlement in section casing ②


1972



LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF - 95 - 2      1971 - 1972

# CORPS OF ENGINEERS

973




## NOTE

Initial datum for settlement of section casing (2)

2. x x x

Measured settlement in section casing (2)




LEHIGH RIVER BASIN  
 POHOPOCO CREEK, PA  
 BELTZVILLE LAKE  
 SUBSURFACE SETTLEMENT DATA  
 VIF - 95 - 2      1973 - 1974



1969


SETTLEMENT  
1 INCH = 0.4'



NOTE  
555.85 (2)




1970




NOTE  
555.85 ② = INITIALLY INSTALLED BOTTOM  
ELEVATION FOR CASING #2

LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF-98-5 1969-1970


# CORPS OF ENGINEERS



NOTE:




1972



LEHIGH RIVER BASIN  
POHOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF-98-5 1971-1972


# CORPS OF ENGINEERS

1973




NOTE

Initial datum for settlement of section casing (2)




Measured settlement in section casing (2)

U S ARMY



LEHIGH RIVER BASIN  
F. IOPOCO CREEK, PA.  
BELTZVILLE LAKE  
SUBSURFACE SETTLEMENT DATA  
VIF-98-5 1973-1974

PLATE 17



1972

1973

MAY JUNE JULY AUG. SEPT. OCT. NOV. DEC. JAN. FEB. MAR. APR. MAY JUNE JULY

WEIR 3


WEIR 2

NO READINGS

NO READINGS

1973


APR. MAY. JUNE JULY AUG. SEPT. OCT. NOV.



LEHIGH RIVER BASIN  
POHOPOCO CREEK, PENNSYLVANIA  
BELTZVILLE DAM & RESERVOIR  
WEIR DISCHARGE







Flow Net Values  $N_f = 7.3$ ,  $N_p = 6.0$

### CASE I.

- \* Water level determined from piezometers ppf-95-5 and 95-6

### Computation of Seepage

$$Q = KH \frac{N_f}{N_p} L \quad K = 0.0002 \text{ fpm}$$

$$q = 0.0002 \times 103 \times \frac{7.3}{6.0} \times 1 = 0.02506 \text{ cfm per ft} = 0.1875 \text{ gpm per ft}$$


$$\text{Valley Section } L = 400 \quad Q = 0.1875 \times 400 = 75 \text{ gpm}$$

$$\text{Left Abutment } L = 180 \quad Q = 0.1875 \times 180 \times \frac{1}{2} = 17 \text{ gpm}$$

$$\text{Right Abutment } L = 400, \text{ Avg } H = 82' \quad Q = \frac{82}{103} \times 0.1875 \times 400 = 60 \text{ gpm}$$

$$\text{Total} = 152 \text{ gpm}$$

$$\text{For } K = 0.00002 \text{ fpm, } Q = 15 \text{ gpm}$$



Flow Net Values  $N_f = 3.6$ ,  $N_p = 11.6$

### CASE 2.

### Computation of Seepage

$$Q = KH \frac{N_f}{N_p} L \quad K = 0.0002 \text{ fpm}$$

$$q = 0.0002 \times 103 \times \frac{3.6}{11.6} \times 1 = 0.00652 \text{ cfm per ft} = 0.04877 \text{ gpm per ft}$$

$$\text{Valley Section } Q = 0.04877 \times 400 = 20 \text{ gpm}$$

$$\text{Left Abutment } Q = 0.04877 \times 180 \times \frac{1}{2} = 4 \text{ gpm}$$

$$\text{Right Abutment } Q = \frac{82}{103} \times 0.04877 \times 400 = 16 \text{ gpm}$$

$$\text{Total} = 40 \text{ gpm}$$

$$\text{For } K = 0.00002 \text{ fpm, } Q = 4 \text{ gpm}$$

30'

of Seepage

002 fpm

0.02506 cfm per ft. = 0.1875 gpm per ft.

$$Q = 0.1875 \times 400 = 75 \text{ gpm}$$

$$Q = 0.1875 \times 180 \times \frac{1}{2} = 17 \text{ gpm}$$

$$H = 82' \quad Q = \frac{82}{100} \times 0.1875 \times 400 = 60 \text{ gpm}$$

Total = 152 gpm

15 gpm

30'

putation of Seepage

K = 0.0002 fpm

$$= \frac{1}{11.4} \times 1 = 0.00652 \text{ cfm per ft.} = 0.04877 \text{ gpm per ft.}$$


$$Q = 0.04877 \times 400 = 20 \text{ gpm}$$

$$Q = 0.04877 \times 180 \times \frac{1}{2} = 4 \text{ gpm}$$

$$Q = \frac{82}{100} \times 0.04877 \times 400 = 16 \text{ gpm}$$

Total = 40 gpm

002 fpm, Q = 4 gpm



LEHIGH RIVER BASIN  
POHOPOCO CREEK, PENNSYLVANIA  
BELTZVILLE LAKE  
FLOW NET ANALYSES  
STATION 9+580

Appendix A

Condition Report


Beltzville Lake


Pohopoco Creek, Pennsylvania






Periodic Inspection Report No. 3 & 4

Supplemental As-Built Drawings

CORPS OF ENGINEERS







1. WORK this plan by month (1958-59)

2. The load of the area extends into the next 15 months and is to be worked in the following manner:

3. 50% of the area is to be worked in the first 15 days of the month and the remainder of the area is to be worked in the next 15 days of the month.

4. The material is to be loaded in the following manner:

5. 50% of the material is to be loaded in the first 15 days of the month and the remainder of the material is to be loaded in the next 15 days of the month.







6. The remainder of the material is to be loaded in the next 15 days of the month.

7. The remainder of the material is to be loaded in the next 15 days of the month.

8. The remainder of the material is to be loaded in the next 15 days of the month.

9. The remainder of the material is to be loaded in the next 15 days of the month.

10. The remainder of the material is to be loaded in the next 15 days of the month.



NAME <i>ALVIN</i>	DOB <i>11/24/41</i>	SSN <i>11-24-41</i>	EMP FLOOR & ASSOCIATES INC CONCRETE FRAMING CO.	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
ADDRESS <i>10111 N. 10th Ave.</i>	CITY <i>PHOENIX</i>	STATE <i>ARIZONA</i>	LOCATION <i>11111 N. 10th Ave.</i>	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
PHONE <i>241-1111</i>	FAX <i>241-1111</i>	TELETYPE <i>241-1111</i>	OUTLET WORKS EXCAVATION - SECTIONS	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
NAME <i>ALVIN</i>	DOB <i>11/24/41</i>	SSN <i>11-24-41</i>	EMP FLOOR & ASSOCIATES INC CONCRETE FRAMING CO.	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
ADDRESS <i>10111 N. 10th Ave.</i>	CITY <i>PHOENIX</i>	STATE <i>ARIZONA</i>	LOCATION <i>11111 N. 10th Ave.</i>	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
PHONE <i>241-1111</i>	FAX <i>241-1111</i>	TELETYPE <i>241-1111</i>	OUTLET WORKS EXCAVATION - SECTIONS	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
NAME <i>ALVIN</i>	DOB <i>11/24/41</i>	SSN <i>11-24-41</i>	EMP FLOOR & ASSOCIATES INC CONCRETE FRAMING CO.	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
ADDRESS <i>10111 N. 10th Ave.</i>	CITY <i>PHOENIX</i>	STATE <i>ARIZONA</i>	LOCATION <i>11111 N. 10th Ave.</i>	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM
PHONE <i>241-1111</i>	FAX <i>241-1111</i>	TELETYPE <i>241-1111</i>	OUTLET WORKS EXCAVATION - SECTIONS	U.S. GROUP ENGINEER AND TRAILER MANUFACTURING CORP. OF ENGINEERS GROUP OF THE BENTLEY SYSTEM



**Top Limit of Left Abutment Cutoff Trench Establishment**  
Exact Limits to be Established in the Field

Coordinates  
N 258,245.5  
E 2,584,122.0


Elevation Scale:  
670  
630  
590  
550  
510  
470

Profile G Labels:  
LBB-118  
Dip of beds 10°-20°  
Top of existing surface  
LBB-98  
Dip of beds 10°-20°  
Dip of beds 20°-30°  
LBB-104  
Dip of beds 20°-30°  
Dip of beds 35°  
Assumed top of relatively firm rock  
Approx limit of left abutment cut off trench excavation Final slope not steeper than 1 on 1

Profile F Labels:  
Top of existing surface  
Assumed top of weathered shale  
Assumed top of relatively firm rock  
Approx limit of excavation

Profile E Labels:  
Top of existing surface  
Assumed top of weathered shale  
Assumed top of relatively firm rock  
Approx limit of excavation

## REVISIONS



, BUILT. DA

~~SECRET~~

U.S. GEOLOGICAL SURVEY  
WASHINGTON, D.C.

DAM  
GEOLOGICAL PROFILE ON AXIS OF DAM

NOV 1960

AD-A112 182

ARMY ENGINEER DISTRICT PHILADELPHIA PA

F/6 13/13

BELTZVILLE LAKE CONDITION REPORT, DAM, OUTLET WORKS AND SPILLWA--ETC(U)

JUN 74

UNCLASSIFIED

DAEN/NAP-01340/PIR0304-74

NL

2 OF 2

ALL A

11/21/74

END

DATE

FORMED

04-82

DTIC







28 25



Resolution Test Chart  
1.0 1.1 1.25 1.4 1.6 1.8 2.0 2.2 2.5 2.8





NOTES:

Work in a training with 3544.

1. *Chlorophyll a* (Chl *a*)

1000

*Journal of Management Education* 30(6)

1. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Arar and Collins (1971) using a Shimadzu 1010 spectrophotometer.

... ..

no. de 3011

[Page 10 of 10]

3. ARMY ENGINEER DISTRICT, PHIL.  
CORPS OF ENGINEERS

OFFICE OF THE DISTRICT ATTORNEY

1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100  
 101  
 102  
 103  
 104  
 105  
 106  
 107  
 108  
 109  
 110  
 111  
 112  
 113  
 114  
 115  
 116  
 117  
 118  
 119  
 120  
 121  
 122  
 123  
 124  
 125  
 126  
 127  
 128  
 129  
 130  
 131  
 132  
 133  
 134  
 135  
 136  
 137  
 138  
 139  
 140  
 141  
 142  
 143  
 144  
 145  
 146  
 147  
 148  
 149  
 150  
 151  
 152  
 153  
 154  
 155  
 156  
 157  
 158  
 159  
 160  
 161  
 162  
 163  
 164  
 165  
 166  
 167  
 168  
 169  
 170  
 171  
 172  
 173  
 174  
 175  
 176  
 177  
 178  
 179  
 180  
 181  
 182  
 183  
 184  
 185  
 186  
 187  
 188  
 189  
 190  
 191  
 192  
 193  
 194  
 195  
 196  
 197  
 198  
 199  
 200  
 201  
 202  
 203  
 204  
 205  
 206  
 207  
 208  
 209  
 210  
 211  
 212  
 213  
 214  
 215  
 216  
 217  
 218  
 219  
 220  
 221  
 222  
 223  
 224  
 225  
 226  
 227  
 228  
 229  
 230  
 231  
 232  
 233  
 234  
 235  
 236  
 237  
 238  
 239  
 240  
 241  
 242  
 243  
 244  
 245  
 246  
 247  
 248  
 249  
 250  
 251  
 252  
 253  
 254  
 255  
 256  
 257  
 258  
 259  
 260  
 261  
 262  
 263  
 264  
 265  
 266  
 267  
 268  
 269  
 270  
 271  
 272  
 273  
 274  
 275  
 276  
 277  
 278  
 279  
 280  
 281  
 282  
 283  
 284  
 285  
 286  
 287  
 288  
 289  
 290  
 291  
 292  
 293  
 294  
 295  
 296  
 297  
 298  
 299  
 300  
 301  
 302  
 303  
 304  
 305  
 306  
 307  
 308  
 309  
 310  
 311  
 312  
 313  
 314  
 315  
 316  
 317  
 318  
 319  
 320  
 321  
 322  
 323  
 324  
 325  
 326  
 327  
 328  
 329  
 330  
 331  
 332  
 333  
 334  
 335  
 336  
 337  
 338  
 339  
 340  
 341  
 342  
 343  
 344  
 345  
 346  
 347  
 348  
 349  
 350  
 351  
 352  
 353  
 354  
 355  
 356  
 357  
 358  
 359  
 360  
 361  
 362  
 363  
 364  
 365  
 366  
 367  
 368  
 369  
 370  
 371  
 372  
 373  
 374  
 375  
 376  
 377  
 378  
 379  
 380  
 381  
 382  
 383  
 384  
 385  
 386  
 387  
 388  
 389  
 390  
 391  
 392  
 393  
 394  
 395  
 396  
 397  
 398  
 399  
 400  
 401  
 402  
 403  
 404  
 405  
 406  
 407  
 408  
 409  
 410  
 411  
 412  
 413  
 414  
 415  
 416  
 417  
 418  
 419  
 420  
 421  
 422  
 423  
 424  
 425  
 426  
 427  
 428  
 429  
 430  
 431  
 432  
 433  
 434  
 435  
 436  
 437  
 438  
 439  
 440  
 441  
 442  
 443  
 444  
 445  
 446  
 447  
 448  
 449  
 450  
 451  
 452  
 453  
 454  
 455  
 456  
 457  
 458  
 459  
 460  
 461  
 462  
 463  
 464  
 465  
 466  
 467  
 468  
 469  
 470  
 471  
 472  
 473  
 474  
 475  
 476  
 477  
 478  
 479  
 480  
 481  
 482  
 483  
 484  
 485  
 486  
 487  
 488  
 489  
 490  
 491  
 492  
 493  
 494  
 495  
 496  
 497  
 498  
 499  
 500  
 501  
 502  
 503  
 504  
 505  
 506  
 507  
 508  
 509  
 510  
 511  
 512  
 513  
 514  
 515  
 516  
 517  
 518  
 519  
 520  
 521  
 522  
 523  
 524  
 525

**DAM**

**TYPICAL SECTIONS SHE**

TYPICAL SECTIONS - SHEET

INVT NO DACW 61-87 B-	NO E	QUANTITY 35491
--------------------------	---------	-------------------

[illegible]

**PLATE 23**





1. **NAME** \_\_\_\_\_

\_\_\_\_\_

---

Contract No DAAG 61-67 C-0224

PLATE 23







G

F

E


D

C

B

A

LINE 1  
LINE 2  
LINE 3  
LINE 4  
LINE 5




ANGLE HOLES UP TO 60' DEEP  
IN C LINE 75' DEEP ON A & B LINE

ANGLE HOLES ON C LINE UP TO 100' DEEP  
PRIMARY HOLES ON A & B 25' DEEP IN C LINE  
SECONDARY HOLES ARE 10' DEEP IN C LINE  
ON A & B LINE AND 25' DEEP IN C LINE TRANSITIONAL  
FROM 100' DEEP


TRANSITIONAL HOLES ON C LINE UP TO 100' DEEP  
CONTACT GROUTING WITH GROUT PAPER REQUIRED IN CONCRETE  
AROUND OUTLET ADRES. FOR DATA SEE LOG NO 35499  
SPOT HOLES IN THE CONDUIT AREA SHALL BE CROSS-CHECKED

**PROFILE ALONG DAM 6**  
SCALE 1"=100'-0"




**MULTIPLE LINE GROUTING PLAN**  
SCALE 1"=100'-0"

- LEGEND
- PRIMARY GROUT HOLES
  - x SECONDARY GROUT HOLES
  - TERTIARY GROUT HOLES



**TYPICAL SECTION**  
NOT TO SCALE



**INSERT 1**  
SCALE 1"=20'-0"



SECTION TAKEN PERPENDICULAR  
TO CENTERLINE OF CONDUIT  
ELEVATION OF TOP OF CONDUIT  
AT CENTERLINE IS 154.85  
ELEVATION OF TOP OF CONDUIT  
AT CENTERLINE IS 154.85

- NOTES
- 1. THE DRAINAGE AND  
FLUX RATE OF  
WILL BE DETERMINED
  - 2. TEST GROUTING  
IN THE FOLLOWING  
AREA A STA 9+0  
AREA B STA 9+0  
THE RESULTS OF  
TESTING
  - 3. TESTS ON DAM  
AND SHALL BE  
ALL PRIMARY AND  
AND GRAVITY DAM

REVISIONS			
NO.	DATE	DESCRIPTION	BY
1	10/1/50	REVISED	J.M. H.
2	10/1/50	REVISED	J.M. H.

### PROFILE ALONG DAM E

SCALE 1"=100'-0"



### GROUT PIPE DETAIL

SCALE 1"=10'-0"

### SECTION

TO SCALE

1. THE DAM AND DEPTH OF HOLES FOR THE CURTAIN GROUTING ARE SHOWN FOR PURPOSE OF ILLUSTRATION. THE ACTUAL SIZING AND DEPTH OF HOLES WILL BE DETERMINED BY THE CONTRACTING OFFICE AS THE WORK PROGRESSES.

2. TEST GROUTING HAS BEEN PERFORMED BY THE CONTRACTING OFFICE IN 900' IN THE FOLLOWING AREAS:

AREA 'A' STA 9+890 TO STA 9+845, AREA 'B' STA 9+820 TO STA 9+800, AREA 'C' STA 9+080 TO STA 9+180.

THE RESULTS OF TEST GROUTING ARE AVAILABLE.

3. EXTENSION PIPE 1 FT LONG SHALL BE REQUIRED FOR EACH GROUTING AS SHOWN AND SHALL BE CONNECTED TO THE MIDDLE PRIOR TO GRouting TO GRouting ALL PRIMARY AND SECONDARY HOLES 'A', 'B', 'C' LINES STA 9+250 DRILL FROM 5' AND GRAVITY GROUTED.

SEE GROUTING RECORDS - PART OF PERMANENT RECORDS AT DAM SITE.

#### NOTES

- THE DAM AND DEPTH OF HOLES FOR THE CURTAIN GROUTING ARE SHOWN FOR PURPOSE OF ILLUSTRATION. THE ACTUAL SIZING AND DEPTH OF HOLES WILL BE DETERMINED BY THE CONTRACTING OFFICE AS THE WORK PROGRESSES.
- TEST GROUTING HAS BEEN PERFORMED BY THE CONTRACTING OFFICE IN 900' IN THE FOLLOWING AREAS:  
AREA 'A' STA 9+890 TO STA 9+845, AREA 'B' STA 9+820 TO STA 9+800, AREA 'C' STA 9+080 TO STA 9+180.  
THE RESULTS OF TEST GROUTING ARE AVAILABLE.
- EXTENSION PIPE 1 FT LONG SHALL BE REQUIRED FOR EACH GROUTING AS SHOWN AND SHALL BE CONNECTED TO THE MIDDLE PRIOR TO GRouting TO GRouting ALL PRIMARY AND SECONDARY HOLES 'A', 'B', 'C' LINES STA 9+250 DRILL FROM 5' AND GRAVITY GROUTED.

SEE GROUTING RECORDS - PART OF PERMANENT RECORDS AT DAM SITE.



BUILT DATE MAY 11/51

U.S. ARMY ENGINEER DISTRICT PHILADELPHIA CORPS OF ENGINEERS OFFICE OF THE DISTRICT ENGINEER LARGE ENGINEER WATERWAYS DIVISION WILTHERVILLE DAM AND RESERVOIR	
DAM GROUTING PLAN & DETAILS	
DESIGNED BY J.M. H.	CHECKED BY J.M. H.
DATE 10/1/50	SCALE AS SHOWN
NO. 55495	DATE 20

CONTRACT NO DACH 61-61-2-0224

## LEGEND

- ▲ PRESSURE CELL
- VERTICAL INCLINATION INSTR.
- PIEZOMETER
- PIE - PIEZOMETER - CUTOFF TRENCH
- PIE - PIEZOMETER - EMBANKMENT
- PIF - PIEZOMETER - FOUNDATION
- VIF - VERTICAL INCL. INSTRUMENT FOUNDATION
- PPE - PRESSURE CELL - EMBANKMENT
- PPF - PRESSURE CELL - FOUNDATION



GAGE NO.	STATION	RANGE	ELEVATION	MATERIAL	TYPE OF INSTALLATION
PIE-77-1	7+770	0+60 UP	610.3	EMBANKMENT	PIEZOMETER
PIE-77-2	7+770	0+7 UP	578.3	CUTOFF TRENCH	"
PPF-77-3	7+770	0+68 DN	584.4	FOUNDATION	PRESSURE CELL
PIE-86-1	8+600	1+35 UP	581.5	"	PIEZOMETER
PIE-86-2	8+600	0+60 UP	596.6	EMBANKMENT	"
PIE-86-3	8+600	0+17 UP	583.0	CUTOFF TRENCH	"
PPF-86-4	8+600	0+88 DN	572.5	FOUNDATION	PRESSURE CELL
PPF-86-5	8+600	1+90 DN	578.5	"	"
PIE-98-1	9+820	1+35 UP	513.1	EMBANKMENT	PIEZOMETER
VIF-98-2	9+820	0+17 UP	515.5	FOUNDATION	VERT. INSTR.
VIF-98-3	9+820	1+35 UP	508.3	EMBANKMENT	PIEZOMETER
VIF-98-4	9+820	0+80 UP	508.5	FOUNDATION	VERT. INSTR.
PIE-98-5	9+820	0+17 UP	501.8	CUTOFF TRENCH	PIEZOMETER
PPF-98-6	9+820	0+80 DN	482.2	FOUNDATION	PRESSURE CELL
VIF-98-7	9+820	0+60 UP	565.9	EMBANKMENT	PIEZOMETER
PIE-98-8	9+820	0+17 UP	582.0	CUTOFF TRENCH	"
PIE-98-9	9+820	0+80 DN	588.2	FOUNDATION	PRESSURE CELL
PPF-98-10	9+820	1+90 DN	498.8	"	"
VIF-98-11	9+820	0+17 UP	550.0	"	VERT. INSTR.
PPE-98-12	9+820	0+80 DN	482.2	FOUNDATION	PRESSURE CELL
PPE-98-13	9+820	1+80 DN	523.8	"	"
PPE-98-14	9+820	0+80 DN	510.2	"	"
PPE-98-15	9+820	1+90 DN	510.2	"	"

MONITOR BOX NO.	STATION	GAUGE	EL. TOP OF BOX
Box 86-1	8+600	1-96.80	611.5
Box 98-1	9+820	0+82.84	534.5




NO. PIE-77-1  
STA. 7+770  
RANGE 0+60 UP  
BOT. EL. 610.3

1/2" 30 HEAD BRASS BOLT

NOTE: IDENTIFICATION TAGS WILL BE PLACED ON ALL PIEZOMETER & VERTICAL INCLINATION INSTALLATIONS.

TOP LENGTH OF PIPE WITH CAP WHEN IS INSTALLED ON TOP OF PIPE AFTER EACH EXTENSION



DETAIL OF IDENTIFICATION TAG  
NOT TO SCALE











PLATE 20


**PRESSURE CELLS-INSTALLATION**

NOT TO SCALE


NOTE  
TEMPORARY G CASING WILL  
BE REQUIRED DURING INSTALLATION

**DETAIL NO. 2**  
NOT TO SCALE**TYPICAL SECTION  
EXCAVATION FOR PRESSURE CELL TUBING**


NOT TO SCALE

**CONCRETE MONITORING BOXES**

NOT TO SCALE


**DETAIL NO. 3**  
NOT TO SCALE



**PROFILE ON S CONDUIT**

Horizontal scale = 1" = 100'  
Vertical scale = 1" = 10'

REVISIONS



## PROFILE ON &amp; CONDUIT

Horizontal scale = 100:1  
Vertical scale = 10:1

LEGEND	
Overburden	<p><b>ALLOUVIUM</b> Recent deposits consisting of pervious sands, gravels and occasional boulders.</p> <p><b>DRIFT</b> Glacially deposited heterogeneous mixture of clay through boulders, compact.</p> <p><b>XUTWASH</b> Glacial, predominantly stratified, silts and silty sands loose.</p>
Bedrock	<p><b>SHALE</b> Weathered highly fragmental, many clay filled joints.</p> <p><b>SHALE</b> Relatively firm, predominantly dk-gray in color same sandstone beds.</p>
	Devonian Mahantong formation

Note: Offset of borings left or right of conduit & reference to downstream stationing.

MAKING

CONTACT NO. 61-67-C-1224

DESIGNED BY H. S. HARRIS	CHECKED BY H. S. HARRIS	DATE 10/1/54
PROJECT OUTLET WORKS CONDUIT GEOLOGIC PROFILE ON & CONDUIT		
DESIGNED BY H. S. HARRIS	CHECKED BY H. S. HARRIS	DATE 10/1/54
PROJECT NO. 35498		


PLATE 28

35 mm




4258,053 133  
E 2,583,848.028


4 100  
A-10, 50 479  
C-584, 17 714




SECTION 4. No. 10000




SECTION A - A



SE. T. N. 33




SECTION E-E



107040

ST. J. DA



Site of dam  
250,053.133  
250,053.028





REVISIONS		DATE	BY
1	Revised for	10/1/54	J. H. H.
2	Revised for	10/1/54	J. H. H.
3	Revised for	10/1/54	J. H. H.
4	Revised for	10/1/54	J. H. H.
5	Revised for	10/1/54	J. H. H.

6+D

Flow arrow pointing right



6+D CONDUIT



SECTION C-C

SECTION D-D

NOTE: Dimensions shown are typical of the structure.


NOTES

1. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
2. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
3. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
4. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
5. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
6. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
7. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
8. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
9. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.
10. Install 12 plates of 1/2 inch thick steel reinforcement in the concrete structure.


SCALE 1" = 10'

DATE 10/1/54


U S ARMY ENGINEER DISTRICT PHILADELPHIA	
CORPS OF ENGINEERS	
OFFICE OF THE DISTRICT ENGINEER	
BELLEVILLE DAM AND RESERVOIR	
OUTLET WORKS	
CONDUIT	
OUTLINE AND REINFORCEMENT	
NO. 35499	DATE 10/1/54
BY J. H. H.	AS SHOWN



PROFILE ALONG NC




PROFILE ALONG CE




PROFILE ALONG SOU


REVISIONS			
NO.	DATE	DESCRIPTION	BY
1		SOUTH EDGE	MADE
2		DELETED	



PROFILE ALONG NORTH EDGE OF SPILLWAY



PROFILE ALONG CENTERLINE OF SPILLWAY



PROFILE ALONG SOUTH EDGE OF SPILLWAY

## SYMBOLS

- ▨ Interbedded siltstone and siltstone with some boulders (Dm)
- ▨ Residual overburden (decomposed shale siltstone and slate) (Dm)
- ▨ Partly weathered bedrock (shale siltstone, slate) Mahantango Formation (Dm)
- ▨ Firm Relative to Unweathered Bedrock (shale siltstone and some boulders) (Dm)

## NOTES


Work this drawing with Dwg. 35555, 35556 and 35557.

BUILT


DESIGNED BY N. B. LEBLANC		CHECKED BY N. B. LEBLANC	
DRAWN BY N. B. LEBLANC		CHECKED BY N. B. LEBLANC	
SCALE 1" = 100'		SCALE 1" = 100'	
SPILLWAY GEOLOGICAL PROFILES SHOWING BERM LOCATIONS			
DATE 1967-06-01		DATE 1967-06-01	
BY N. B. LEBLANC		BY N. B. LEBLANC	
NO. 35555		NO. 35556	

CONTRACT NO. DWRM 167-C 2624

### PLAN-CHUTE AND CONTROL SLABS






SECTION A-A



## REVISIONS


1	Added notes to the following drawings & details and revised drawings in place & made available April 1967	USA
2	Revised drawings in place & made available April 1967	USA




SECTION B-B




TRANSVERSE CONSTRUCTION JOINTS - TYPICAL




WEEP DRAINS - TYPICAL



SECTION C-C



LONGITUDINAL CONSTRUCTION JOINTS - TYPICAL




TYPICAL SECTION THRU BRIDGE PIER FOOTING

## NOTES

1. All dimensions are in feet and inches.
2. All dimensions are to be maintained as shown.
3. All dimensions are to be maintained as shown.
4. All dimensions are to be maintained as shown.
5. All dimensions are to be maintained as shown.
6. All dimensions are to be maintained as shown.
7. All dimensions are to be maintained as shown.
8. All dimensions are to be maintained as shown.
9. All dimensions are to be maintained as shown.
10. All dimensions are to be maintained as shown.

CONCRETE STRUCTURES  
OUTLINE AND REINFORCEMENT-SHEET 1


DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES
DESIGNED BY J. H. HARRIS	CHECKED BY J. H. HARRIS	DATE 1967	PROJECT CONCRETE STRUCTURES





SECTION F - F




Actual Plans  
of Anchor Wall Southside Spwy  
Showing Thickness Variation








SECTION N-N





SECTION J - J



SECTION M - M





**DETAIL B**



DETAIL D

SECTION P-P



SECTION H-H

NOTES

1. Work this drawing with 35560 & 35552
2. Contraction joints shall be coated with  $\frac{1}{8}$ " bituminous cement
3. All exposed edges of concrete and contraction joints shall be chamfered  $\frac{1}{8}$ "

RECEIVED FROM FILE BY  
BROOKER MFG CO EAST VYRA, PA

(On left flys 1 m. 13A, w.  
Green - Winston No. 83 (79 C.A.)



RF JUEL Final Dwgs set  
BROCKER No. 4913-14, 14


CONTRACT NO. DAWN 61-61-C-0222

DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.
DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.	DATE TIME LOCATION PROJECT DRAWING NO. SHEET NO.




CORPS OF ENGINEERS





# **SECTION OF BRIDGE**

Scale: 1" = 20'-0"  
 5'-0" 20' 40'-0"



# **PLAN**



Scale: 1" = 1'-0"  
 1' 7' 3' 10' 15' 20'

Set 1 1/2" x 1/2" brass plugs in non-shrink grout at elevation of deck. Scribe center line of bridge in plug after plugs are in place.

U. S. ARMY

REVISIONS


NO.	DATE	DESCRIPTION
1		Revised piers and temporary excavation
2		Added cross plugs for instrumentation



END VIEW

Scale: 1/2" = 1'-0"

12' 0' 1' 2' 3' 4' 5' 6'




ERN FLOOR & ASSOCIATES, INC. CONSULTING ENGINEERS		U.S. ARMY ENGINEER DISTRICT, PHILADELPHIA CORPS OF ENGINEERS OFFICE OF THE DISTRICT ENGINEER	
CHARGE		ILLUSTRATION	
LEHIGH RIVER BRIDGE POTSDAM, NEW YORK BELTZVILLE LAKE			
SERVICE BRIDGE ELEVATION AND STRUCTURAL DETAILS SHEET 1			
DESIGN NO.	SIZE F	PROJECT NO.	35562
DATE AS NOTED		SHEET 37	


PLATE 38

13

## CORPS OF ENGINEERS



ELEVATION OF BRIDGE  
Scale 1" = 20'-0"



P - A N • *Ind. disc*  
Scale  $\frac{1}{4}'' = 1:0''$





U. S. ARMY

REVISIONS	
SYM	DESCRIPTION
4	Added cross plugs for instrumentation

Location	Top of Pier or Abut	Top of Leveling R
North Abutment	694.74*	694.95
Pier No. 1, Span No. 1	690.78	691.02
Pier No. 2, Span No. 2	690.78	690.96
Pier No. 3, Span No. 2	686.79	687.03
Pier No. 4, Span No. 3	686.79	686.97
South Abutment	682.83*	683.04

\* On E of bearing



U. S. ARMY ENGINEER DISTRICT, PHILADELPHIA CORPS OF ENGINEERS OFFICE OF THE DISTRICT ENGINEER		
LEHIGH RIVER BASIN PONDPOOD CREEK, PENNSYLVANIA BELTZVILLE LAKE		
SPILLWAY BRIDGE ELEVATION AND STRUCTURAL DETAILS SHEET 1		
SIZE F	INV. NO.	DRAWING NO. 38896
SCALE AS NOTED		SHEET 121

Appendix B

Condition Report

Beltzville Lake

Pohopoco Creek, Pennsylvania

Periodic Inspection Report No. 3 & 4

List of Attendees - Periodic Inspection Nos. 3 & 4

Keltzville Lake

List of Attendees - Periodic Inspection No. 3

A. Carrabino	NAD - Engineering Division
A. J. Mezeika	NAD - Operations Division
C. J. Lewis	NAD - Engineering Division
M. H. Gross	NAD - Engineering Division
H. S. Lenahan	NAD - Engineering Division
B. I. Uibel	NAD - Engineering Division
G. A. Countryman	NAD - Operations Division
J. T. Borchik	NAD - Operations Division

List of Attendees - Periodic Inspection No. 4

F. J. Coppinger	NAD - Engineering Division
T. Thompson	NAD - Engineering Division
J. Smutz	NAD - Operations Division
A. A. Depphilippe	NAD - Engineering Division
R. W. Greene	NAD - Engineering Division
B. I. Uibel	NAD - Engineering Division
M. H. Gross	NAD - Engineering Division
H. S. Rubright	NAD - Engineering Division
G. A. Countryman	NAD - Operations Division
J. T. Borchik	NAD - Operations Division



ATE  
LMED  
-8